

**ORIGINAL MANUFACTURER EVALUATION REPORT ON USED XCMG CONSTRUCTION MACHINERY**

<b>Equipment Description</b>		Little damage on appearance;used to do stone work; main parts are in good condition, without repairing; 100,000 CNY	
<b>Inspector</b>		Xu Sheng	<b>Inspector</b>
<b>Equipment Status</b>		stocked	<b>Location</b>
<b>Inspect Location</b>		Xuzhou Economic Development Zone, Jiangsu	<b>Date (YYYY/MM/DD)</b>
<b>Basic Information</b>	<b>Machinery</b>	excavator	<b>Manufacturer</b>
	<b>Model</b>	XE215C	<b>Serial Number</b>
	<b>Working Hours</b>	6666h	<b>Manufactured Year</b>
	<b>Certification On XCMG Used Machinery</b>	<input checked="" type="checkbox"/> Non accident machine <input checked="" type="checkbox"/> Non refurbishing machine <input checked="" type="checkbox"/> Non overhaul machine <input type="checkbox"/> Non crushing operation <input type="checkbox"/> Non stonework operation	
<b>Certificate</b>	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N		
	<b>Invoice</b>		<input checked="" type="checkbox"/> Y <input type="checkbox"/> N
	<b>Work With Hammer</b>		<input checked="" type="checkbox"/> Y <input type="checkbox"/> N
<b>Overall Appearance</b>	<b>Operator Cabin</b>	<input checked="" type="checkbox"/> normal <input type="checkbox"/> deformed <input type="checkbox"/> corrosive <input type="checkbox"/> repair <input type="checkbox"/> paint repair <input type="checkbox"/> SEVD	
	<b>General Appearance-Left</b>	<input checked="" type="checkbox"/> normal <input type="checkbox"/> deformed <input type="checkbox"/> repair marks <input type="checkbox"/> multi site repair <input type="checkbox"/> severe deformation <input type="checkbox"/> missing door <input type="checkbox"/> paint repair	
	<b>General Appearance-Righ</b>	<input checked="" type="checkbox"/> normal <input type="checkbox"/> deformed <input type="checkbox"/> repair marks <input type="checkbox"/> multi site repair <input type="checkbox"/> severe deformation <input type="checkbox"/> missing door <input type="checkbox"/> paint repair	
	<b>Boom And Arm Appearance</b>	<input checked="" type="checkbox"/> normal <input type="checkbox"/> deformed <input type="checkbox"/> repair marks <input type="checkbox"/> worn pin bushing <input type="checkbox"/> multi site repair <input type="checkbox"/> seriously worn pin bushing <input type="checkbox"/> SEVD	
	<b>Bucket</b>	<input checked="" type="checkbox"/> normal <input type="checkbox"/> slightly worn <input type="checkbox"/> seriously worn	
	<b>Dozer Blade</b>	<input checked="" type="checkbox"/> normal <input type="checkbox"/> intact <input type="checkbox"/> slightly worn <input type="checkbox"/> seriously worn <input type="checkbox"/> deformed	
<b>Engine</b>	<b>Model</b>	Isuzu 6BG1	<b>Radiator</b>
	<b>Overhauled Machine</b>	<input type="checkbox"/> Y <input checked="" type="checkbox"/> N <input type="checkbox"/> unknown	<b>Complete Nameplate</b>
	<b>Oil / Fuel Leaks</b>	<input checked="" type="checkbox"/> Y <input type="checkbox"/> N	<b>Engine Exhaust</b>
<b>Hydraulic System Status</b>	<b>Boom Cylinder</b>	<input checked="" type="checkbox"/> normal <input type="checkbox"/> slightly oil leaks <input type="checkbox"/> cylinder damage <input type="checkbox"/> SEVD <input type="checkbox"/> serious oil leaks	
	<b>Arm Cylinder</b>	<input checked="" type="checkbox"/> normal <input type="checkbox"/> slightly oil leaks <input type="checkbox"/> oil cylinder damage <input type="checkbox"/> SEVD <input type="checkbox"/> seriously oil leaks	
	<b>Bucket Cylinder</b>	<input checked="" type="checkbox"/> normal <input type="checkbox"/> slightly oil leaks <input type="checkbox"/> oil cylinder damage <input type="checkbox"/> SEVD <input type="checkbox"/> seriously oil leaks	
	<b>Left Traveling Motor</b>	<input checked="" type="checkbox"/> normal <input type="checkbox"/> oil leaks <input type="checkbox"/> poor movement	<b>Right Traveling Motor</b>
	<b>Hydraulic Pump</b>	<input checked="" type="checkbox"/> normal <input type="checkbox"/> oil leaks <input type="checkbox"/> abnormal noise	<b>Rotary /Slewing /Swivel Motor</b>
	<b>Main Control Valve</b>	<input checked="" type="checkbox"/> normal <input type="checkbox"/> slightly oil leaks <input type="checkbox"/> partial oil pipe replacement <input type="checkbox"/> seriously oil leaks <input type="checkbox"/> most of oil pipe replacement	
	<b>Chassis Status</b>	<b>Rotary Clearance</b>	<input checked="" type="checkbox"/> normal <input type="checkbox"/> small clearance <input type="checkbox"/> excessive clearance
<b>Guide Wheel</b>		<input checked="" type="checkbox"/> normal <input type="checkbox"/> large inner diameter clearance <input type="checkbox"/> worn	
<b>Chain Link</b>		<input checked="" type="checkbox"/> normal <input checked="" type="checkbox"/> large chain link clearance <input type="checkbox"/> worn	
<b>Drive Wheel/Sprocket</b>		<input checked="" type="checkbox"/> normal <input type="checkbox"/> slightly worn <input type="checkbox"/> seriously worn	
<b>Track Shoe</b>		<input checked="" type="checkbox"/> slightly worn <input type="checkbox"/> moderately worn <input type="checkbox"/> seriously worn	
<b>X Frame</b>		<input checked="" type="checkbox"/> normal <input type="checkbox"/> damaged <input type="checkbox"/> SEVD	

